

CABLE OXIDE REMOVAL BRUSH



**ORB – 1** PVC black (for identification) for use on copper conductors to remove copper oxide film prior to crimping of cable lugs.

**ORB – 2** PVC white (for identification) for use on aluminium conductors to remove aluminium oxide film prior to crimping of cable lugs

This is a safe and efficient method for removing oxide film from conductors.